m/003/050

Gold Star Stone P. O. Box 62 Oakley, Idaho 83346

January 29, 2002

Mr. D. Wayne Hedberg Permit Supervisor Division of Oil, Gas, and Mining P. O. Box 145801 Salt Lake City, Utah 84114-5801

Re: Response to DOGM review of December 26, 2001 regarding Gold Star Stone, Inc., Lone Pine

Quarry, M/003/050, Box Elder County, Utah

Dear Wayne:

Enclosed is the response to the Division's review of December 26, 2001 regarding Gold Star Stone's Lone Pine Quarry. We have addressed only the items contained in the review; with one exception. The text has been retyped, and submitted in full for the items requiring a response. All changed or added text has been underlined. If it is not underlined, it has not been changed.

No changes were required for Rules R647-4-106.3 and R647-4-107.6. They were not included for this response. One paragraph addressing soil/subsoil stockpiles that was under Rule R647-4-107.5 has been moved to R647-4-106.5 because that is where the review question was asked. The paragraph was underlined because it was moved; however there were no changes to the text.

Rules R647-4-111.8 and R647-4-112 were added to this response because of the review question addressed under R647-4-111.8 which referred to R647-4-110.2. We felt that if these rules were not addressed now, another review would be sent requiring a response to these rules.

Map C-2 was revised to show the West Quarry and the East Quarry at the same scale of 1'' = 200', and to address the question asked under R647-4-107.5. Map E-2 was added to show the roads discussed under R647-4-110.2, R647-4-111.8, and R747-4-112. Map E-3 was added to address the question asked under R647-4-105.3. No changes were made to any other maps; therefore they are not being submitted with this response.

We hope our responses have adequately addressed the Division's questions.

Sincerely,

David J. Ryzak for Bruce Mitchell

David J. Ryzak

Enclosures

cc: Bruce Mitchell

RECEIVED

JAN 3 1 2002

DIVISION OF OIL, GAS AND MINING